

Safety Recall

Chaperone Infant Car Seats

Britax Model #	Fashion
E9L692J	CHAPERONE BLACK/SILVER
E9L692K	CHAPERONE RED
E9L692L	CHAPERONE COWMOOFLAGE
E9L692M	CHAPERONE GREEN

Manufacturing Dates: Between September 1, 2010 and April 30, 2011

The harness adjuster ensures that the harness straps can be properly tightened and secured over the infant shoulders and is attached to the infant car seat shell. The rivet used to attach the harness adjuster to the shell may have been improperly installed. As a result, the harness adjuster may detach from the shell. Should the harness adjuster detach from the infant car seat shell the harness straps will not properly secure the child resulting in increased risk of injury in a vehicle crash.

If the harness adjuster on your Chaperone Infant Car Seat detaches, please discontinue use of the product immediately and contact our Customer Service Department at 1-888-427-4829.



Contact Britax Child Safety, Inc. to receive free harness adjuster clip kit at:

(888) 427-4829

or visit www.ChaperoneRecall.com